Program Tiers

Bronze
requirements
One credentialed
resource
for one capability

Silver requirements
Two credentialed
resources
for minimum of two
capabilities

Gold requirements
Three credentialed
resources
for minimum of
three capabilities

Platinum
requirements
Four credentialed
resources
For minimum of
four capabilities

The Batch Capability is intended to promote a System Integrators' expertise in delivering solutions leveraging Rockwell Automation Batch product offering. The PlantPAx capability is a prerequisite to obtaining the Batch capability.

The training is available and posted to the System Integrator learning plan on Rockwell Automation University (RAU)

Requirements to receive capability
1. **Obtain the Control, Visualization and PlantPAx Capability**   2. **Complete the training as outlined below**

Training Module	Platform	Course length (minutes)
PRC24603 Demonstrating FactoryTalk Batch Material Tracking	RAU	22
PRC24604 Demonstrating FactoryTalk Batch Manual Procedures	RAU	7
PRC21507 PlantPAx Batch Solutions	RAU	25
System Implementation – FactoryTalk® Batch v14 – Applications Development Lab	onCourse	120
Controller-based Batching Using SequenceManager™	onCourse	120
Distributed Batch Deploying Controller-based Sequences with FactoryTalk Batch	onCourse	120
Total Batch Training (hours)		7